

EPA 40 CFR Part 68 RISK MANAGEMENT PLAN (RMP) SEMINAR

FEBRUARY 25, 2004

PORTLAND, OREGON

Overview

The Process Safety and Reliability Group Inc. (www.psrgroup.com) is pleased to announce that it will be holding a Risk Management Plan (RMP) Seminar in Portland, Oregon on February 25, 2003 from 8:30 AM to 3:30 PM at the Radisson near the Portland airport to provide helpful information on how to update and evaluate your existing risk management plan to comply with the 5-year resubmission requirements of the U.S. Environmental Protection Agency (USEPA) RMP Rule (40 CFR 68) and recently published EPA RMP Resubmission Requirements. Speakers will include professionals from industry, EPA Region 10, and other organizations. This course is designed for personnel responsible for completing and/or managing RMPs in the Oil & Gas, Petrochemical/Chemical, Pharmaceutical, Food Processing, Fertilizer, Ammonia Refrigeration, Agricultural, Pulp & Paper, Water/Wastewater Treatment, and other RMP-covered facilities.

Workshop Description

Under 112(r) Accidental Release Prevention Requirements of the Clean Air Act Amendments and EPA 40 CFR 68, facilities having "regulated substances" were required to submit a Risk Management Plan (RMP) to the EPA by June 1999. RMPs are required to be updated and resubmitted every five years; therefore, this means the majority of plans will require resubmission in 2004. This Seminar is intended to provide participants with information on how to timely and cost effectively complete and submit RMPs to ensure compliance with EPA resubmission requirements and how to implement an effective accidental release prevention program.

In this 1-Day Seminar, you will learn about the following topics:

- Overview of the EPA RMP Regulation (40 CFR 68)
- NEW RMP Resubmission Requirements and Data Elements - 68 Fed. Reg. 45123 (July 31, 2003)
- Regulatory Perspective/Status Update from EPA Region 10
- Interpretations and Guidance since June 1999
- Lessons Learned and Practical Tips from Implementing RMP/PSM
- How to Prepare for an RMP Resubmission
- How to Determine Existing Compliance Deficiencies and Resource Requirements
- Offsite Consequence Analysis Guidance (*including information on how to use EPA Lookup and Model OCA Tables; EPA Model programs, PHAST, TRACE, and other tools; Landview V; how to select the right tools/models for OCA; how to identify receptors; etc.*)
- Using EPA's RMP*Submit* to Update your RMP
- How to Keep your RMP "Evergreen" to Make Updates Easier
- Panel Discussion Q&A

Speakers will include:

- Calvin Terada – Risk Management Program Coordinator, EPA Region 10
- Harry Bell – Risk Management Program Specialist, EPA Region 10
- Suzanne Powers – EPCRA Enforcement Coordinator, EPA Region 10
- Robert Hofstra – PSRG, Houston Texas

The Seminar will be moderated and presented by PSRG experts with practical, interactive Workshop "examples" to enhance learning.

Who Should Attend

- Facility RMP/PSM Managers and Coordinators
- Environmental, Health & Safety professionals
- Plant Managers, Engineers
- Consultants, Technical Specialists
- Anyone responsible for RMP compliance at your corporation or facility

Date

Wednesday, February 25, 2004

8:30 AM to 3:30 PM

Sign-in/coffee starts at 8 AM

Breakfast, Lunch, and Break/Snacks provided.

Location

Radisson - Airport Portland OR

6233 NE 78th Court

Portland OR 97218

Tel: 503-251-2000

Seminar Fee

\$195 per Person (Contact PSRG for information on discounts for multiple persons from the same facility.)

Fee includes a comprehensive Seminar Manual, including valuable RMP assessment tools and resources and regulatory references. Breakfast, lunch and AM/PM break refreshments included. Credit Cards accepted.

For Registration or More Information

Please contact PSRG at 713-849-9460 (1-800-250-8511) or via Email) psrghouston@psrgroup.com